## Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Version: CIISF 2017 R0

Issued: 12/15/2017

Effective: 12/15/2017 Status: Active Date: 3/20/19 \_\_\_\_Instrument Serial Number: \_\_\_ Instrument Location: GICOWOOC Supervisor Name and Agency: Brand Bamett Describe the Status Change or Issue with the Instrument: If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: Out of Service Date/Time: For Use by SCDL Additional Notes

## Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

## Barnett, Brandi M (DPS)

Subject:

FW: Tank Change for new Girdwood instrument.

From: Jean Achee [mailto:jachee@whittieralaska.gov]

Sent: Monday, March 11, 2019 10:59 AM

To: Barnett, Brandi M (DPS)

Subject: Re: Tank Change for new Girdwood instrument.

Yes, the Girdwood instrument ended up with two VOCs. When I installed the nalco bottle in the replacement instrument and turned on the power it immediately went into VOC mode before I could input the bottle S/N and expiration date. I then did a second VOC after to input the bottle S/N and expiration date.

J. Achee Police Officer Whittier Police Department

PO Box 687

Whittier, Alaska 99693

Office: (907) 472-2340 Fax: (907) 472-2344

"This communication, including attachments, is for the exclusive use of the person or entity to which it is addressed and may contain confidential, proprietary and/or privileged information. Any review, re-transmission, dissemination or other use of, or taking of any action in reliance upon this information by persons or entities other than the intended recipient is prohibited. If you receive this in error, please contact the sender by return e-mail and delete this from any computer."

On Fri, Mar 8, 2019 at 8:44 AM Barnett, Brandi M (DPS) <br/> strandi.barnett@alaska.gov> wrote:

I noticed that you have two VOC's and 1 tank change record for the install of the new girdwood instrument. I am assuming that you put the tank in prior to turning the instrument on and ran a VOC for the first one and then realized the lot number was incorrect and did the tank change to correct it. Is that what happened. If it is can you verify that the lot number on the first VOC should have been the same as the lot on the second VOC and I will line correct it on that VOC before we sign it.

Thanks	•
--------	---

Brandi

Brandi M. Barnett

Forensic Scientist III

Alaska Scientific Crime Detection Laboratory

907-269-5695