Alaska Scientific Crime Detection Laboratory

I E	ssued: 1/13/2017 Effective: 1/17/2017	DataMaster Check In Form Version: DMCIF	
Instr	rument S/N/00376	Received From	cus: Active
Date	04/10/20	Analyst Deren Watton	
1.	Reason for instrument retu	rn: ment rationished by factory, File while	my in field
2.	Change instrument and ca	se location in JusticeTrax Breath Alcohol Database	
3.	Ensure change in instrume	nt status form is in JusticeTrax	
4.	Upload	Instrument was not in the field	d. DW 04/10/20
5.	Update agency information	and polling status in DM Host Calling Program	
6.	Check for VOCs		
	From Intoximeters		
7.	Intoximeters Repair Papers	rork (attached)	

Intoximeters

Experience · Service · Integrity

Service Record

SRO Number: SRO-039502

Received Date: 03/12/2020

Completion Date: 04/01/2020

SRO Type: REPAIR

SRO Description: DMT Repair/Prev Maint

Customer ID: C000003651

Customer PO: 20200108DJW

Contact: Derek Walton

Email: derek.walton@alaska.gov

Ship To:

Units on SRO

Alaska Scientific Crime Detection Laboratory

4805 Dr MLK Jr Ave Anchorage AK 99507 USA

LEGDMT LEGACY DMT

Service Line	**All Instruments are Calibrated to Factory Specifications**				
Unit Type	: (LEGDMT)	LEGACY DMT	actory openications		
Serial Number	: 50100376	V Ruid	04/10/20		
Reason	on: Preventive Maintenance				
	planned				
Reason Notes:	Preventive Maintenance				
Resolution:	on: Prev M				
	planned				
Resolution Notes: Install digital pot Mod to Control Board Rebuild filter assembly and add epoxy to motor wires Optimize detector Clean and adjusted 5-way valve Applied metal seal tape to the sample chamber mirror blocks. Adjust tech screen settings and RFI sensitivity Added o ring to end of breath tube Leak Checked Parts 001199-00 3.3volt regulator for control board Calibration solution (0.200) Lot# 19200 Bottle# 388 Dry gas:AG916303, Tank 014, Exp. 12 JUN 2021					
Parts:	Otv	Part Number	Part Description		
	1	001199-00	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN		
Reason:	DMT Status M	essages	The reduction v LDO 3.3V OUT 30V IN		
	FltWl er				
Reason Notes:	Customer Repo	orted Issue: filter wheel erro	or		
Resolution:					
	Manla - J:				
	Mech adj				
	3	pricated filter wheel assemble 190-8000-00	ıbly		