## Alaska Scientific Crime Detection Laboratory

## DataMaster Check In Form

Issued: 7/10/2015 Version: DMCIF 2015 R1 Effective: 7/10/2015 Status: Active Instrument S/N /003-15 Received From NPAS Analyst Colleen O'Bryant 9/29/15 1. Reason for instrument return: Returned from MDAS 2. Change instrument and case location in JusticeTrax Breath Alcohol Database 3. Ensure change in instrument status form is in Justice Trax 4. Upload 11/14 5. Update agency information and polling status in DM Host Calling Program 6. Check for VOCs MIA

## From NPAS

7. NPAS Repair Paperwork (attached)

Work Ord No	49859
Date	8/18/15

Work Ord No 49859 Date 8/18/15		Service Acti	National Patent Analytical Systems, Inc. Service Action Report		
Customer	Alaska Dept of I	Public Phone 907-2	269-5582 <sup>Con</sup>	<sup>stact</sup> Bolz	
War Exp	/13/13	Mx Exp	Ship Damage? O	Y 🗿 N Cust Pick U	p??
shipping dan	ents: note any nage or estimate ng with accessor				
	blem seen and/o nents received	r UNIT WAS FLOOD	DED WITH ACETONE,	THIS IS BILLABLE	
Keyword	······································				
Finding :		Error Code	Enter Hours	2.0	
Repair Comr Performed	nents and work	Replaced all contamin Set voltages, calibrat		•	ed unit.
Solution Lo	t No <u>15040</u>	· · · · · · · · · · · · · · · · · · ·			
	Voltage	Set Values In	Voltage Set Valu	es Out	1
	Lamp 1.830	O Brth Vol	Lamp 1.620	Brth Vol 1.540	
	Meter 3.336	) Filter Dif	Meter 0.221	Filter Dif 0.662	
	Stability		Stability 0.001		
Part No	Qty Ord Pict	Back Total Ordered sbin	Description		Price Ea
26002r	1,0	S	VC ITEM 26002		5.1 <u>.</u> 50
		Fitting,	CPC Panel Mnt Male		
28527	1.0	C	ONN TERM BLOCK 6 POS	2.54MM CTR	5.460
30277r	2.0	S	VC ITEM 30277	<del>ay tananga</del> <u>a ya man jayanangan</u>	13.650
<u></u>	·	Fitting,	CPC Panel Mnt Female		
30367	1.0	F	ITTING, CPC PANEL MNT	MODIFIED (r30277)	23.740
41139	1.0	S	AMPLE CHAMBER ASS'Y,	dmt FLAT CAP	368.200

			Fitting, CPC Panel Mnt Male	
28527	1.0		CONN TERM BLOCK 6 POS 2.54MM CTR	5.460
302771	2.0		SVC ITEM 30277 Fitting, CPC Panel Mnt Female	13.650
30367	1.0		FITTING, CPC PANEL MNT MODIFIED (r30277)	23.740
41139	1.0	1	SAMPLE CHAMBER ASS'Y, dmt FLAT CAP	368.200
41214	1.0		TUBE ASSY, DM CDM BREATH DM W/41460	88.480
41248	1.0		PUMP ASSY, dmt 12VDC	202.830
41259	1.0		MASS AIR FLOW WIRED ASS'Y (SVC)	113,080
41267	1.0		VALVE ASSY, BASIC BLOCK & SLIDE ASSY	100.410
41503	1.0		VALVE ASSY, CHECK PURCHASED ASSY.	37.800
41504r	1.0		SVC ITEM 41504 Valve Assy, Dual Check	19.540
9DMT	1.0		DATAMASTER DMT SERVICE RETURN 100345	***************************************

T 21	9859 3/18/15	Na	National Patent Analytical Systems, Inc. Service Action Report			Serial No 100345		
Customer	laska Dept	of Public	Phone 907-26	9-5582	Contact Bolz			
War Exp 1	/13/13		Mx Exp	Ship Damage?	O Y 💿 N	Cust Pick Up	?? OY <b>O</b> N	
nitial Comme shipping dam required, alor	nage or estin	nates	THIS IS BILLABLE					
Describe prol attach docum			UNIT WAS FLOODED	WITH ACETON	E, THIS IS BIL	LABLE		
Ceyword Finding			: Error Code	Enter Ho	ours 2.0			
Repair Comn Performed	nents and wo		laced all contaminat voltages, calibrated			. Inspecte	d unit.	
Solution Lo	t No 15040							
<b>f</b>	Vo	ltage Set Valu	alues In Voltage Set Values Out					
	Lamp 1	.830	Brth Vol	Lamp 1.620	Brth Vol	1.540		
	Meter 3	.330	Filter Dif	Meter 0.221	Filter Dif	0.662		
	Stability			Stability 0.001	· · · :			
Part No	- Qty Ord	PRK	Back Total dered shin	Description			Price Ea	
NOTE	1.0		BRE	ATH TUBE				
NOTE	1.0	:	NAN	IUK CASE			***************************************	
r500-1	1.0	÷ :	Sen	vice Charge for Rep	pair		119.000	
r500-2	1.0	:	Sen	rice Charge for Rep	pair, Additional I	Hours	109.000	
<u>( </u>	***************************************		<u> </u>				<del></del>	