

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 1/31/2025

Instrument #: 100697

Instrument Location: South Processing Room Anchorage Jail

Supervisor Name and Agency: Jason Cusack, Anchorage Police Department

Describe the Status Change or Issue with the Instrument:

I was notified of several RFI detected status messages received over the past few days. I then had an interference detected status message on the external standard. I rebooted the instrument, disconnected the breath hose, and then reconnected the breath hose. I then conducted two non-drinking subject tests and did not run into any other problems.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: [Click or tap here to enter text.](#)

Out of Service Date/Time: [Click or tap here to enter text.](#)

For Use by SCDL

Additional Notes

Verified 16 consecutive RFI messages from 1/29/25 through 1/31/25. Instrument appears to be working normally as of Ofc. Cusack's reboot and reseating the breath hose connections on 1/31/25. Further evaluation of this issue will occur with the next In Field Instrument Review cycle. Most subjects were able to be successfully tested on other APD-assigned DataMasters. Neither other APD-assigned DataMaster experienced a similar issue during the date range in question. DJW 02/03/2025

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor