

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 12/15/2017  
Effective: 12/15/2017

Version: CIISF 2017 R0  
Status: Active

Date: 5/30/18 Instrument Serial Number: 100424

Instrument Location: Fielson AFB

Supervisor Name and Agency: Colleen O'Bryant, SCDL

Describe the Status Change or Issue with the Instrument:

Fielson was experiencing RFI status messages following the instrument being moved to a different room. The instrument was relocated and the RFI status messages stopped.

COB 5/30/18

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: NA

Out of Service Date/Time: NA

For Use by SCDL

Additional Notes

---

---

---

---

---

---

---

---

---

---

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740

**O'Bryant, Colleen S (DPS)**

---

**From:** LAMOUREUX, CYLE J SSgt USAF PACAF 354 SFS/CSS <cyle.lamoureux@us.af.mil>  
**Sent:** Wednesday, May 30, 2018 10:55 AM  
**To:** O'Bryant, Colleen S (DPS)  
**Cc:** JORDAN, JUSTIN R TSgt USAF PACAF 354 SFS/S3FOC; VAUGHN, CHAD S SMSgt USAF PACAF 354 SFS/S3O  
**Subject:** RE: DataMaster Issues

Colleen,

We successfully moved the DataMaster into a separate room. I ran a non-drinking subject test to completion with no status messages, and ran a VOC to completion.

I'm verifying whether or not the phone number has changed for the scheduled tests.

Thank you for all of your help!

V/R

Cyle

-----Original Message-----

**From:** O'Bryant, Colleen S (DPS) [mailto:colleen.obryant@alaska.gov]  
**Sent:** Wednesday, May 30, 2018 10:25 AM  
**To:** LAMOUREUX, CYLE J SSgt USAF PACAF 354 SFS/CSS <cyle.lamoureux@us.af.mil>  
**Cc:** JORDAN, JUSTIN R TSgt USAF PACAF 354 SFS/S3FOC <justin.jordan.7@us.af.mil>; VAUGHN, CHAD S SMSgt USAF PACAF 354 SFS/S3O <chad.vaughn.1@us.af.mil>  
**Subject:** [Non-DoD Source] RE: DataMaster Issues

Cyle,

Any luck with moving the instrument and testing for RFI again?

Colleen

-----Original Message-----

**From:** O'Bryant, Colleen S (DPS)  
**Sent:** Thursday, May 24, 2018 5:39 PM  
**To:** LAMOUREUX, CYLE J SSgt USAF PACAF 354 SFS/CSS <cyle.lamoureux@us.af.mil>  
**Cc:** JORDAN, JUSTIN R TSgt USAF PACAF 354 SFS/S3FOC <justin.jordan.7@us.af.mil>; VAUGHN, CHAD S SMSgt USAF PACAF 354 SFS/S3O <chad.vaughn.1@us.af.mil>  
**Subject:** Re: DataMaster Issues

Could you temporarily move the instrument to a location you know isn't effected by RFI, maybe an out of the way office, and run a non-drinking subject test? The room doesn't need to have a phone line, we're just troubleshooting.

Colleen

> On May 24, 2018, at 5:14 PM, LAMOUREUX, CYLE J SSgt USAF PACAF 354 SFS/CSS <cyle.lamoureux@us.af.mil> wrote:

>  
> Colleen,  
>  
> After attempting to run a non-drinking test, we encountered the same "RFI detected" status message. There are no radios in the room, however, our Armory is across the hall and they charge radios there around the clock. I also believe our building's radio antenna sits above the room. The only thing I can fathom is that these are causing the status messages. I am going to sit down with our Operations staff to discuss moving the DataMaster (once again), to a location further from these areas to see if it resolves the problem. If the phone number changes, I will absolutely forward the updated number for scheduled VOCs.  
>  
> V/R  
>  
> CYLE J. LAMOUREUX, SSgt, USAF  
> NCOIC, Administrative Support  
> 354 Security Forces Squadron  
> DSN: 377-1119  
> Comm: (907) 371-4226  
>  
>