Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Version: CIISF 2017 R0 Effective: 12/15/2017 Status: Active

Date:	Instrument Serial Number:
Instrument Location:	
Supervisor Name and Agency	:
Describe the Status Change or	Issue with the Instrument:
-	rvice or removed from service, fill out the appropriate sections below.
in Service Date/Time	
Out of Service Date/Time:	
For Use by SCDL	
See attached documentation	DJW 06/03/2021

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Walton, Derek J (DPS)

From: O'Bryant, Colleen S (DPS)

Sent: Wednesday, June 2, 2021 12:08 PM

To: Barnett, Brandi M (DPS); Walton, Derek J (DPS)

Subject: Fwd: MSW datamaster

Thoughts on sending MSW a new instrument?

Begin forwarded message:

From: "Steen, Pete C (DPS)" <pete.steen@alaska.gov>

Date: June 2, 2021 at 12:03:01 PM AKDT

To: "O'Bryant, Colleen S (DPS)" <colleen.obryant@alaska.gov>, "Barnett, Brandi M (DPS)"

<brandi.barnett@alaska.gov>

Cc: "Phillips, Lee E (DPS)" < lee.phillips@alaska.gov>

Subject: MSW datamaster

Ladies,

The Datamaster at MSW is down. Threw a pump error yesterday while doing the VOC and after restart just gave me a fatal software error and restarted again. This is past my knowledge base to fix and will need to be replaced.

Steen

Walton, Derek J (DPS)

From: Barnett, Brandi M (DPS)

Sent: Wednesday, June 2, 2021 1:35 PM

To: Walton, Derek J (DPS); O'Bryant, Colleen S (DPS)

Subject: RE: Datamaster restarting

Sounds good.

Brandi M. Barnett Chemistry Supervisor Scientific Director - Breath and Blood Alcohol Program Alaska Scientific Crime Detection Laboratory 907-269-5695

From: Walton, Derek J (DPS) <derek.walton@alaska.gov>

Sent: Wednesday, June 2, 2021 1:34 PM

Subject: FW: Datamaster restarting

Since the screen also froze with the first pump error (prompting the first restart), I do think this rises to the level of replacement.

Derek Walton

Forensic Scientist

State of Alaska Scientific Crime Detection Laboratory

From: Steen, Pete C (DPS) <pete.steen@alaska.gov>

Sent: Wednesday, June 2, 2021 1:32 PM

To: Walton, Derek J (DPS) <derek.walton@alaska.gov>

Subject: RE: Datamaster restarting

I did restart it following a pump error and frozen screen. After that it seemed to do ok and went into the timed event before a test could be run and I had to leave it yesterday. Today when I got back I attempted to see what was going on with it and when I tried to push the NPAS menu button at the top it immediately gives me some kind of fatal error and restarts the instrument. I have shut it down now.

Steen

Sent from Mail for Windows 10

From: Walton, Derek J (DPS)

Sent: Wednesday, June 2, 2021 1:29 PM

To: Steen, Pete C (DPS)

Subject: Datamaster restarting

Hi Trp. Steen,

If I understood your email correctly, the Datamaster had pump error on the VOC so you restarted it. Then after restarting it, it produced a fatal error and restarted itself?

Did you attempt to run a second VOC after the second restart? One off pump errors are fairly common and not necessarily something we'd remove an instrument for. A one off fatal error is not that common, but if it recovered OK we may consider leaving the instrument in the field if it passes a VOC and seems normal otherwise.

I know you talked to Colleen already, just trying to get a bit more information to make an informed decision. Thanks for your time,

Derek Walton

Forensic Scientist III – Chemistry Seized Drugs Technical Lead State of Alaska Scientific Crime Detection Laboratory Derek.walton@alaska.gov (907)269-5628