Alaska Scientific Crime Detection Laboratory

DataMaster Evaluation Form

Effective: 10/10/2022		Version: 3.0
Instrument #:	Analyst(s	s): Deren Watten
Reason for instrument evaluation Not registering breath	during subj	jet Sample
Visual Inspection Clean		☑ Replace missing screws
Cermetex Box (modem) is sec	cure	Ensure modem cable present
Double Check Valve secured to	o wall	All tubing and connections secure
O-ring inspection and ensure 2	2 replacemer	nt O-rings in bag
As Found Conditions: Barometric Pressure (inHg): Linearity Test (attached)	_Temperatu	ure (C):Relative Humidity (%)
0.020g/210L Mnf:	Lot:	Exp:
0.080g/210L Mnf: 0.300g/210L Mnf:		Exp: Exp:
Notes		Is repair. No further testing at
VOC (attached)VOC Internal Standard value ≤ 3.		erify software version on-Drinking Subject Test (attached)
Condition of item: Good	, Needs Repair	-
☐ Ready for Adjustment☐ Ready for Calibration		
End Date: 11/19/22		
All printed copies are uncontrolled.	Page 1 of 1	Approved by: Chemistry Supervisor