Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014 Version: CIISF 2014 R0 Status: Active

	100400
Date: 8-17-16 Instru	ment Serial Number: 106700 0038/18/16
Instrument Location: Palmer PD	
Supervisor Name and Agency: Luke Se	ipsohj Palme PD
Describe the Status Change or Issue with the Inst	trument: du tomaster due to
TOTTING CIP IC	Cooks .
If instrument was placed in service or removed fr	om service, fill out the appropriate sections below.
In Service Date/Time:	
Out of Service Date/Time:	736
For Use by SCDL Additiona	l Notes
gas flow excess were first ((220psi) Tank was chang gas flow errors, instrument precourter it would occur	seen on a low pressure tank, and on 7/11/10. No longer (sow) removed from verifice out of again with a low pri tank.

Email completed form to

For questions contact the Breath Alcohol Program at 907-269-5740