## Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 6/11/2014 Version: CIISF 2014 R0 Effective: 6/11/2014 Status: Active

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

## Foster, Charles R (DPS)

From: Foster, Charles R (DPS)

Sent: Friday, December 08, 2017 11:05 AM

To: vgaray@ci.galena.ak.us

Cc: O'Bryant, Colleen S (DPS); Barnett, Brandi M (DPS)

Subject: 100398 - Galena PD - APC not holding charge during power outages

Attachments: Change in Instrument Status Form 2014 R0.pdf

Below is a link to the battery you need to purchase for your APC unit. I clicked the "Where to Buy" button and it looks like Amazon has them in stock.

http://www.apc.com/shop/us/en/products/APC-Replacement-Battery-Cartridge-2/P-RBC2

Attached is the Change in Instrument Status form that you need to fill out. Out of Service should be the date and time the power went out. When you install the new back up battery, plug the Datamaster back in, turn it on, and initiate a VOC. When the VOC completes successfully, put the date and time on the In Service section of the Change in Instrument status form. Email the form to <a href="mailto:dps.scdl.toxicology@alaska.gov">dps.scdl.toxicology@alaska.gov</a> after completing it.

Thank you, Chuck