

Alaska Scientific Crime Detection Laboratory
Change in Instrument Status Form

Version: 6.0

Effective: 1/17/2024

Date: 3/13/25

Instrument #: 100675

Instrument Location: ANGOON

Supervisor Name and Agency: AST - Luke Lemieux

Describe the Status Change or Issue with the Instrument:

Will NOT complete a VOC without a status message. Failed diagnostic check and pump not working

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time:

Out of Service Date/Time: 3/13/25 1200 Hours

For Use by SCDL

Additional Notes

Internal standard error and pump on/off during diagnostic. DJW 03/14/2025

Email completed form to dps.scdl.toxicology@alaska.gov.

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor