Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Version: CIISF 2017 R0 Status: Active

Date: 1/17/20	Instrument Serial Number: 10055
Instrument Location: A	NGOOD
Supervisor Name and Agend	ey: UMBS/AST
Describe the Status Change	or Issue with the Instrument: service to be sent to Crime Laboratory maintenance.
For preventive	maintenance.
If instrument was placed in s	service or removed from service, fill out the appropriate sections below.
In Service Date/Time:	
	1-17-2020 1006 HRS
out of service Date Time.	
For Use by SCDL	Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740