Alaska Scientific Crime Detection Laboratory

DataMaster Check In Form

Issued: 1/13/2017 Version: DMCIF 2017 R0 Effective: 1/17/2017 Status: Active Instrument S/N 100359 Received From Intoximeters, Inc. Date_05/21/2019 Analyst Derek Walton 1. Reason for instrument return: Instrument refurbished by manufacturer 2. Change instrument and case location in JusticeTrax Breath Alcohol Database 3. Ensure change in instrument status form is in JusticeTrax 4. Upload \Box 5. Update agency information and polling status in DM Host Calling Program \(\textstyle \) \(\textstyle \) 6. Check for VOCs \(\simeta\)/A From Intoximeters

7. Intoximeters Repair Paperwork (attached)

Order Packing Slip Report

5/15/2019 2:14:57 PM

Intoximeters

Experience · Service · Integrity

Packing Slip: 175503

SRO: SRO-032435

Pack Date: 5/15/2019

From: Intoximeters, Inc 2081 Craig Road St Louis MO 63146

USA

Customer: C000003651

Ship To: 1

Alaska Department of Public Safety

4805 Dr MLK Jr Ave

Anchorage AK 99507

USA

Alaska Department of Public Safety

4805 Dr MLK Jr Ave Anchorage AK 99507

USA

Customer PO: 01092019-Walton

Ship Via: FDX

FED EX

Weight: 29.00

Delivery Terms: 2D

FOB: ORIGIN

Packages: 1

Customer Ship Account:

Maricachorea

INTOX

Intoximeters, Inc

Page 1 of 2

Order Packing Slip Report

Intoximeters
Experience · Service · Integrity

5/15/2019 2:14:57 PM

CONTRACT PREV MAINT DMT

Intoximeters

Experience · Service · Integrity

Service Record

SRO Number: SRO-032435

Received Date: 01/09/2019

Completion Date: 05/02/2019

SRO Type: ESTIMATE

SRO Description: DMT Repair

Customer PO: 01092019-Walton

Customer ID: C000003651

Email: derek.walton@alaska.gov

Contact: Derek Walton

Ship To:

Units on SRO

Alaska Department of Public Safety

4805 Dr MLK Jr Ave Anchorage AK 99507

USA

LEGDMT LEGACY DMT

Service Line:	**All Instruments are Calibrated to Factory Specifications**			
Unit Type:	(LEGDMT) LEGACY DMT			
Serial Number:	50100359			
Reason:	DMT Status Messages			
	StcAnaly			
Reason Notes:	Customer Reported Issue: Static analysis			
	Contact Dan w/Estimate			
Resolution:	Replaced			
	RPL comp			
	Broke down and cleaned IR bench. Replaced one mirror block that was scratched. Replaced Teflon tape on inlet and outlet. Reattached check valve to side cover Replaced filter wheel solenoid Replaced filter wheel solenoid mounting screw Moved filter wheel wiring to pump top Adjusted tech screen settings Adjusted RFI sensitivity Calibrated			

Parts:	<u>Qty</u>	Part Number	Part Description		
	1	59-0114-00	DMT HRDW SHOULDER BOLT 30490		
Reason:	DMT Status Messages				
	Intl Std				
Reason Notes:	Customer Reported Issue: Internal standard error,				
Resolution:	Adjusted				
	Mech adj				
Resolution Notes:	Rebuilt filter wheel assembly, cleaned and lubricated. After rebuild of FWA and IR bench, and recalibrate, Internal Std cleared.				
	1	59-0000-09	DMT HRDW MIRROR MOUNT ASSY FLAT 41374		
Reason:	DMT Status Messages				
	IntrSubs				
Reason Notes:	Customer Reported Issue: Tank interference				
Resolution:	ReCal				
	Cal IR				
Resolution Notes:	Recalibration	n after cleaning and service	cleared interference on dry gas.		
	1	59-0113-00	DMT HRDW TUBE SILICON 36009		
Reason:	DMT Functional				
	Hi Temp				

Intoximeters

Experience · Service · Integrity

Service Record

Reason Notes:	IR bench reporting high temperature			
Resolution:	Replaced			
	RPL comp			
Resolution Notes:	Replaced IR bench temperature sensor			
	1	59-0083-00	DMT ELEC LAMP ASSY IR TO -8 41630	
Reason:	DMT Functional			
	DigPots			
Reason Notes:				
Resolution:	Update			
	DMTVR3			
Resolution Notes:				
	1	59-0055-00	DMT ELEC DETECTOR PCB ASSY 41601	
Reason:	DMT Mechanical or Physical			
	DGasdrop			
Reason Notes:				
Resolution:	Update			
	Update			
Resolution Notes:	Replaced regulator with updated version			
	1	001199-00	DMT ELEC REGULATOR V LDO 3.3V OUT 30V IN	
	1	59-0080-00	DMT ELEC ASSY SOLENOID FILTR WHEEL 41344	
	1	001217-00	DMT HRDW GAS MOUNT ASSY W/VALVE	