Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Version: CIISF 2017 R0 Status: Active

Date: 04/25/2020	Instrument Serial Number: 100675
Instrument Location: Bethel PD -	Patrol Room
Supervisor Name and Agency:	
Describe the Status Change or 100675 is being placed into service at BP	Issue with the Instrument: D. Sent to replace a prior instrument.
	y .
If instrument was placed in se In Service Date/Time: 04/24/20	rvice or removed from service, fill out the appropriate sections below.
For Use by SCDL	Additional Notes

Email completed form to dps.sedl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740