Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Effective: 12/15/2017 Version: CIISF 2017 R0

Status: Active

Instrument Serial Number: 100668 Instrument Location: Palmer PD Supervisor Name and Agency: Luke Szipszky Describe the Status Change or Issue with the Instrument: tatal system error If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: Out of Service Date/Time: 8/311800 For Use by SCDL Additional Notes

Email completed form to dps.sedl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740