Alaska Scientific Crime Detection Laboratory

Issued: 04/03/2018 Effective: 04/04/2018	Version: DMEF2018 R0 Status: Active
Instrument # 100367 Date: 01/09/20	Analyst: Derew Watton
1. Reason for instrument evaluation Pump emors with	in simulator use
 2. Visual Inspection Clean Cermetex Box is secure Gas Valve upright or secured to 	Replace missing screws See 12/16/19 Ensure modem cable present Pralvation to wall All tubing and connections are secure
will be returned	rings in replacement bag whole cause of pump errors with simulator nt factory refurbished in September, 2019. I to factory under parts and labor terms ment contract.
 5. VOC (attached) 6. Internal Standard value ≤ 3.00% 7. Verify software version □ 	NA Yes No
Return to Factory for Repair	Ready for Calibration
Ready for Certification	☐ Proceed to Close Out