

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017
Effective: 12/15/2017

Version: CIISF 2017 R0
Status: Active

Date: 11/2/2021 Instrument Serial Number: 100398

Instrument Location: Anchorage PD

Supervisor Name and Agency: Carlie Flaister

Describe the Status Change or Issue with the Instrument:

100398 was transferred from Breath Test section to APD on 10/11/2021.
A tank change & VOC was performed on 10/13/2021. This date was used as the in service date.

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: 10/13/2021

Out of Service Date/Time: _____

For Use by SCDL

Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740