Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Effective: 11/10/2021 Version: 2.0
Date: 7 Jone 2022 Instrument #: B-100255
Instrument Location: Clear 585
Supervisor Name and Agency: Sones, Kwin 268th 5F5
Describe the Status Change or Issue with the Instrument: Instrument recently taken ast of service for filter wheel error. Temporary Patamaster arrived 7 June to replace until repairs made.
If instrument was placed in service or removed from service, fill out the appropriate sections below.
In Service Date/Time:
Out of Service Date/Time: 7 June 2022 / 1415 hrs
For Use by SCDL Additional Notes 100255 2022.05.12 Change In Status documents the Instrument being removed from service after failed trouble starting on 5/12/2022. No additional forts were ferfivmed between 5/12/2022 & Col 7/2022. This change in instrument form documents the instrument being turned of unphased a proved up to be returned after reviewing the repacement Data master. (Vit 1/11/2022)

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor