Alaska Scientific Crime Detection Laboratory Change in Instrument Status Form Effective: 11/10/2021 Version: 2.0 Date: 03-28-2022 Instrument #: 100356 Instrument Location: 6170 Wood Supervisor Name and Agency: Mark Hage Whittier PD Describe the Status Change or Issue with the Instrument: New Instrument If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: 03-28-2022 1115 Out of Service Date/Time: Additional Notes For Use by SCDL On 03-29-22, Officer Hager called about the instrument not warming up and the BT temp showing up as 0.0. He was first advised to restart the PMT, then to plug & unplug the breath hose then ensure it's completely plugged in . This fixed the issue.

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1

All printed copies are uncontrolled. Approved by: Chemistry Supervisor