Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014 Version: CIISF 2014 R0 Status: Active

Date: 10 20 20	Instrument Serial	Number:	00352
Instrument Location:	Bestel AST		
Supervisor Name and Age	ncy: Nick HAMES	AST	
Describe the Status Change	e or Issue with the Instrument: will not accept breath	sample.	
		·····	
	service or removed from service,		
	10/20/2015/0000		propriate sections below.
In Service Date/Time:	10/20/2015/0000		
In Service Date/Time: Out of Service Date/Time:	10/20/2015 /0900 11/24/2005 /1700		
In Service Date/Time: Out of Service Date/Time:	10/20/2015 /0900 11/24/2005 /1700		

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 6/11/2014 Version: CIISF 2014 R0 Status: Active

Date: 1/24/2015	Instrument Serial Number: 100 35 7
	settle AST
Supervisor Name and Agency:	Nick HAMES / AST
Describe the Status Change or I	
If instrument was placed in servi	ce or removed from service, fill out the appropriate sections below.
Out of Service Date/Time:	1/10/2015 /0720 BMB 4/1/16 out of service voc 11/24/15 see in and out of service paperwork for correct date.
For Use by SCDL	Additional Notes

Email completed form to dps.scdl.toxicology.orglaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740