

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 12/15/2017  
Effective: 12/15/2017

Version: CIISF 2017 R0  
Status: Active

Date: 01/12/2020 Instrument Serial Number: 100369

Instrument Location: Bethel PD - Patrol Room

Supervisor Name and Agency: Justin Ulak

Describe the Status Change or Issue with the Instrument:

Instrument was sent to replace another with gas flow error. Placed into service.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: 12/26/19

Out of Service Date/Time: \_\_\_\_\_

For Use by SCDL	Additional Notes
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740

# Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 12/15/2017  
Effective: 12/15/2017

Version: CIISF 2017 R0  
Status: Active

Date: 2/13/2020 Instrument Serial Number: 100369

Instrument Location: Bethel PD

Supervisor Name and Agency: Colleen O'Bryant, SCDL

Describe the Status Change or Issue with the Instrument:

---

---

---

---

---

---

---

---

---

---

If instrument was placed in service or removed from service, fill out the appropriate sections below.

In Service Date/Time: NA

Out of Service Date/Time: NA

-----  
**For Use by SCDL**

**Additional Notes**

The instrument was certified on 12/17/2019 and shipped to Bethel PD and placed in service on 12/26/2019. The attached change in instrument status form from Justin Ulak indicates it was placed in service in Bethel on 12/26/2019. An in service VOC was not performed on 12/26/2019. I contacted Justin Ulak to confirm that the correct external standard lot number was entered into the DMT. See the attached pictures for Justin's documentation that the serial number on the tank matched that entered into the DMT. Justin then replaced the tank back into the DMT which prompted a verification of calibration.

A scheduled verification of calibration was performed on 01/03/2020. Another verification of calibration occurred on 1/23/2020 and Justin's was performed following the tank verification on 02/06/2020.

Email completed form to [dps.scdl.toxicology@alaska.gov](mailto:dps.scdl.toxicology@alaska.gov)

For questions contact the Breath Alcohol Program at 907-269-5740

