Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Issued: 12/15/2017 Version: CIISF 2017 R0 Effective: 12/15/2017 Status: Active

Date: 01/12/2020	Instrument Serial Number: 100347
Instrument Location: Bethel PD - Pa	atrol Room
Supervisor Name and Agency: Justin Ulak - Between PD	
Describe the Status Change or Is	sue with the Instrument: detector overflow errors. The new instrument experienced gas flow error. The troubleshooting steps
were taken but still unsuccessful.	
If instrument was placed in servi	ce or removed from service, fill out the appropriate sections below.
Out of Service Date/Time: 12/22/	2019, 0700
For Use by SCDL	Additional Notes
Instrum	ent 100347 out of sense on 12/22/19 due to
	900 flow errors. Apr 01/17/20

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740