Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Version: CIISF 2017 R0

Issued: 12/15/2017

Effective: 12/15/2017 Status: Active Instrument Serial Number: 100687 Instrument Location: 1868 KAGAK ST, OTOHAGULK, AK, 98723 Supervisor Name and Agency: KEUN KELSON Describe the Status Change or Issue with the Instrument: REPLACING DIMT 1003917 WITH TANK CHANGE FROM 100397 100687 EXP: 8/22/2021 LOT# AG923401 TANK. SEND NEW If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: ___ Out of Service Date/Time: For Use by SCDL Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740