Alaska Scientific Crime Detection Laboratory Change in Instrument Status Form

Version: 4.5

Effective: 10/10/2022

Date: 7/31/2023	Instrument #: 100371
Instrument Location: Whittier PD	
Supervisor Name and Agency: Carlie Glaister SCDL	
Describe the Status Change or Issue with the Instrument:	
While reviewing VOC's, I noticed that the tank lot# was incorrect for the 2023.07.03 and 2023.07.18 VOCs. In addition to the two VOCs there is 1 subject test on 2023.07.28 with the incorrect tank lot #. The agency Breath Test Supervisor, Mark Hager, was contacted to correct the lot # on 2023.07.31. The tank was promptly removed and then re-installed with the correct lot # This was verified by reviewing the VOC performed afterwards on 2023.07.31. The lot # on the breath test is unable to be corrected.	
If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: Click or tap here to enter text.	
Out of Service Date/Time: Click or tap here to enter text.	
For Use by SCDL	Additional Notes
Click or tap here to enter text.	

Email completed form to <u>dps.scdl.toxicology@alaska.gov</u>
For questions contact the Breath Alcohol Program at 907-269-5740

Page 1 of 1

All printed copies are uncontrolled.

Approved by: Chemistry Supervisor