## Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Issued: 12/15/2017 Version: CIISF 2017 R0 Effective: 12/15/2017 Status: Active

| Date: 1/31/18   | Instrument Serial Number: 100370  |
|---|---|
| Instrument Location: Juneau                                     | PD  |
| Supervisor Name and Agen  | y: Sterling Salisbury JPD   |
|   |   |
| Describe the Status Change<br>This is a new unit received today | or Issue with the Instrument:<br>rom the lab. It has been placed in service with a VOC immediately completed. |
|   |   |
|   |   |
|   |   |
|   |   |
|   |   |
|   |   |
|   | ervice or removed from service, fill out the appropriate sections below.  2200 hours $\frac{1}{3!}/18$        |
|   |   |
| For Use by SCDL   | Additional Notes  |
|   |   |
|   |   |
|   |   |
|   |   |
|   |   |
|   |   |

Email completed form to <a href="mailto:dps.scdl.toxicology@alaska.gov">dps.scdl.toxicology@alaska.gov</a>

For questions contact the Breath Alcohol Program at 907-269-5740