Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form Issued: 6/11/2014 Version: CIISF 2014 R0 Effective: 6/11/2014 Status: Active

5-13-15 Instrument Serial Number: 100688 Instrument Location: SOLDOTNA AST Supervisor Name and Agency: TRP- M-WERT AN EN Describe the Status Change or Issue with the Instrument: REPLATIONE BROKEN DMJ. OLD UNIT SENT TO LAB. If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: 5-13-15 | 2136 Out of Service Date/Time: For Use by SCDL Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740