Alaska Scientific Crime Detection Laboratory

Change in Instrument Status Form

Version: CIISF 2017 R0

Status: Active

Date: 1-13-19 Instrument Serial Number: 00355 Instrument Location: Homen P.D. Supervisor Name and Agency: Jim Kroff Homen Pips Describe the Status Change or Issue with the Instrument: In strument into denvice If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: 1-13-19 / 1634 hours Out of Service Date/Time: For Use by SCDL Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Issued: 12/15/2017

Effective: 12/15/2017