## Alaska Scientific Crime Detection Laboratory

## Change in Instrument Status Form

Version: CIISF 2014 R0

Status: Active

\_\_\_ Instrument Serial Number: 100687 Instrument Location: Supervisor Name and Agency: Drandt remotely with operator Bu Describe the Status Change or Issue with the Instrument; Placed instrument in spric If instrument was placed in service or removed from service, fill out the appropriate sections below. In Service Date/Time: \_ Out of Service Date/Time: For Use by SCDL Additional Notes

Email completed form to dps.scdl.toxicology@alaska.gov

For questions contact the Breath Alcohol Program at 907-269-5740

Issued: 6/11/2014

Effective: 6/11/2014